



Regions Affected: EUROPE

Dear Customers and Colleagues,

In January of 2016 Honeywell launched the MIDAS O2S 3-year sensor (MIDAS-L-O2S), with the purpose of providing customers with a more reliable and cost-effective solution for O2 detection.

Following the success of that launch, Honeywell will discontinue both the legacy standard and extended O2X sensor (part number MIDAS-S-O2X and part number MIDAS-E-O2X) for manufacturing in 2020. This announcement is to alert you of our plans to discontinue these products and to provide a last-time purchase opportunity for them.

- Both the standard and extended MIDAS O2X sensor will be available for order through March 31, 2020, after which time no new unit orders will be accepted. Final shipments for new orders will be June 30, 2020.

- Consistent with our commitment to support existing customers, Honeywell will honour warranty replacements for both the standard (1 year, PN: MIDAS-S-O2X) and extended (2 year, PN: MIDAS-E-O2X) MIDAS O2X sensor with the MIDAS O2S 3-year sensor (PN: MIDAS-L-O2S), starting June 2020.

Products Impacted

- Standard Midas O2X sensor (part number: MIDAS-S-O2X)
- Extended MIDAS O2X sensor (part number: MIDAS-E-O2X)